New Jersey Department of Transportation FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM	Project ID Numbers
ROOTE/T ROOKAW	DB No. TIP No.

17 Central Avenue Bridge, Rochelle Park

94056

94056

LOCATION/DESCRIPTION

Bridge over Central Avenue, proposed replacement

This project will provide for the proposed bridge replacement which was identified by Bridge Management System. The overall condition of the bridge is serious, with low appraisal ratings for structural elevation and the inadequate deck geometry warrant replacement with widening.

SPONSOR: NJDOT
COUNTY: Bergen
MILEPOSTS: 10.90

STRUCTURE NO.: 0214159

МРО	Phase	Year
NJTPA	CD	2002
NJTPA	FA	2003

17 Corridor, Williams Avenue to Garden State Parkway

103

103

LOCATION/DESCRIPTION

Williams Avenue to Garden State Parkway, corridor study

A corridor study will be undertaken which may result in widening to a consistent sixlane cross-section, replacement or rehabilitation of structures, interchange and other improvements.

SPONSOR: NJDOT
COUNTY: Bergen
MILEPOSTS: 8.00 - 13.60
STRUCTURE NO.: N/A

MPO	Phase	Year
NJTPA	CD	2002
NJTPA	FA	2003

New Jersey Department of Transportation FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM

Project ID Numbers
DB No. TIP No.

East Passaic Street Bridge

94048

94048

LOCATION/DESCRIPTION

Bridge over East Passaic Street, proposed bridge replacement

This project will provide for the proposed bridge replacement which was identified by the Bridge Management System. The overall condition of this structure is listed as critical due to the low inventory ratings. Due to the low appraisal rating for structural evaluation, deck geometry, and underclearances, bridge replacement is recommended.

SPONSOR: NJDOT COUNTY: Bergen MILEPOSTS: 11.50

17

STRUCTURE NO.: 0214160

MPO	Phase	Year
NJTPA	CD	2002

17 NYS&W Bridge

94057

94057

LOCATION/DESCRIPTION

Bridge over the New York, Susquehanna, and Western Railroad, proposed rehabilitation or replacement

This proposed bridge rehabilitation or replacement was identified by Bridge Management System. The overall rating of the structure is fair due to the condition of the superstructure and the inadequate deck geometry.

The federal Transportation Equity Act for the 21st Century (TEA-21) provided funding for this project under Section 1601, High Priority Projects Program. The Act allocated \$1.13 M for this project. FY 2000 and FY2001 RABAs have increased the total authorization amount to \$1,154,626.

SPONSOR: NJDOT COUNTY: Bergen MILEPOSTS: 10.90

STRUCTURE NO.: 0214157

МРО	Phase	Year
NJTPA	CD	2002
NJTPA	FA	2003

New Jersey Department of Transportation FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM	Project I	D Numbers
	DB No.	TIP No.

17 Plaza Way Bridge

94058

94058

LOCATION/DESCRIPTION

Bridge over Plaza Way, proposed replacement

This proposed bridge replacement was identified by the Bridge Management System. Due to the low inventory ratings, the overall condition of the structure which is listed a critica, replacement is recommended.

SPONSOR: NJDOT
COUNTY: Bergen
MILEPOSTS: 11.60

STRUCTURE NO.: 0214161

МРО	Phase	Year
NJTPA	CD	2002
NJTPA	FA	2003

17 Railroad Avenue, Drainage

93174

93174

LOCATION/DESCRIPTION

Railroad Avenue in vicinity of railroad bridge (northbound only), proposed drainage improvement

Identified drainage problems result in periodic flooding in the vicinity of the railroad bridge. Conditions noted include an inadequate drainage system even though the tidal wataer is below normal level; above-normal tides cause closure of the northbound roadway.

SPONSOR: NJDOT
COUNTY: Bergen
MILEPOSTS: 4.93
STRUCTURE NO.: N/A

MPO	Phase	Year
 NJTPA	FA	2002
NJTPA	FSD	2003